



IAS

International
Aviation
Services Ltd

Beechcraft - Super King Air 200 Serial Number BB-82

For Sale



Very well maintained JAR-OPS compliant Aircraft.
Maintenance during last 10 years in Beechcraft service centre, Augsburg, Germany

Utilization up to 06-DEC-2011

Airframe	7181:15 FLIGHT HRS; 5499 FLIGHT CYCLES
Engine No.1 PT6A-41 S/N PCE-80164,	7141:05 ENGINE HRS, 6126 ENGINE CYCLES
Engine No.2 PT6A-41 S/N PCE-81257	14849:12 ENGINE HRS, 14500 ENGINE CYCLES
Propeller No.1 HC-B3TN-3G/T10178B-3R S/N BUA22810	7181:15 PROP HRS, 5499 PROP CYCLES
Propeller No.2 HC-B3TN-3G/T10178B-3R S/N BUA23420	7181:15 PROP HRS, 5499 PROP CYCLES

Maintenance

Maintenance	Date/Aircraft FHRS/FCYC	Component FHRS/FCYC
Propeller No.1 HC-B3TN-3G/T10178B-3R S/N BUA22810 Overhaul	29-AUG-2011 7175:45 Airframe FHRS 5485 Airframe FCYC	7175:45 FHRS 5485 FCYC
Propeller No.2 HC-B3TN-3G/T10178B-3R S/N BUA23420	29-AUG-2011 7175:45 Airframe FHRS	7175:45 FHRS 5485 FCYC



IAS

**International
Aviation
Services Ltd**

Overhaul	5485 Airframe FCYC	
Airframe Complete Cycle - Phase 1-4 (Biennial Inspection Program)	27-SEP-2011 7175:45 Airframe FHRS 5485 Airframe FCYC	N/A
200 Flight HRS Lubrication	27-SEP-2011 7175:45 Airframe FHRS 5485 Airframe FCYC	N/A
5000 Flight Cycles Frame Web Inspection	27-SEP-2011 7175:45 Airframe FHRS 5485 Airframe FCYC	N/A
Engine No.1 PT6A-41 S/N PCE-80164 Complete Cycle - Phase 1-4 (Biennial Inspection Program); 200 FHRS Lubrication; first 100 FHRS inspection	27-SEP-2011 7175:45 Airframe FHRS 5485 Airframe FCYC	Engine TSN: 7135 HRS Engine CSN: 6143 CYC
Engine No.2 PT6A-41 S/N PCE-81257 Complete Cycle - Phase 1-4 (Biennial Inspection Program); 200 FHRS Lubrication; first 100 FHRS inspection	27-SEP-2011 7175:45 Airframe FHRS 5485 Airframe FCYC	Engine TSN: 14842:42 HRS Engine CSN: 14487 CYC
Engine No.1 PT6A-41 S/N PCE-80164 Overhaul	09-NOV-2011 7179:45 Airframe FHRS 5419 Airframe FCYC	Engine TSN: 7139 HRS Engine CSN: 6147 CYC
Engine No.2 PT6A-41 S/N PCE-81257 Overhaul	09-NOV-2011 7179:45 Airframe FHRS 5419 Airframe FCYC	Engine TSN: 14746:42 HRS Engine CSN: 14421 CYC

Next Due Maintenance:

Phase 1-4 (Biennial Inspection Program)	Due: 27-SEP-2012, 7375 FHRS
Propeller No.1 HC-B3TN-3G/T10178B-3R S/N BUA22810 Overhaul	Due: 29-AUG-2016
Propeller No.2 HC-B3TN-3G/T10178B-3R S/N BUA23420 Overhaul	Due: 29-AUG-2016
Engine No.1 PT6A-41 S/N PCE-80164 Overhaul	10039 ENGINE HRS
Engine No.2 PT6A-41 S/N PCE-81257 Overhaul	17746:42 ENG HRS

High flotation landing gear

- Equipment:**
- A/P Sperry SPZ 200
 - Garmin GNS-430 GPS/COM/NAV
 - Collins VHF-20
 - HF
 - ADF - DME - A/P-flight dir - RNAV - RMI
 - Radar - prop sync - strobes - full de-ice
 - AD's / SB's complied

Additional avionics modifications:

1. GNS-430 navigating system.
2. 8.33 Spacing / FM Immunity
3. Mode S, elementary, level II transponders TDR-94D
4. ELT C-406-2
5. Satellite phone - AeroPhone® IRIDIUM

New Exterior Paint in 2005



IAS

International
Aviation
Services Ltd

Interior completely refurbished in 2005

Dark green leather seats

Configuration 8 passenger

FWD: LH single seat, RH 3 person couch

AFT: 4 single seats business configuration with foldable tables between

Kitchen compartment with oven

Aft cabin sliding door separating cabin from toilet

WC compartment

Audio entertainment system

Interior:





IAS

International
Aviation
Services Ltd



Exterior:



Sofia Airport
Block 3, floor 3
1540, Sofia, Bulgaria

Phone +359 2 945 90 35
Fax: +359 2 851 06 71
Cell: +359 887 461 779

E-mail: office@ias-eu.com
www.ias-eu.com